


5/5



NOTE : ALL METAL SURFACES SHALL BE PAINTED WITH REDOXIDE PRIMER FOR FIRST COATING, QDE GLOSS FOR FINAL COATING.

DET. "A"  
SCALE 1:10 M